




Cobra SPX 5300 Buttons Replacement

Replace the buttons of your Cobra SPX 5300 Radar Laser Detector.

Written By: Fanny Auad



INTRODUCTION

Use this guide if the buttons of your Cobra SPX 5300 aren't working correctly.



TOOLS:

- [Phillips #0 Screwdriver](#) (1)
 - [Phillips #00 Screwdriver](#) (1)
-

Step 1 — Windshield Bracket Mount



- Remove the four 9.5 mm Phillips #0 screws from the back of the device.

Step 2



- Pull the black plastic back case off of the device.


Step 3



- Lift up the motherboard and lay it flat next to the device.


⚠ Be careful not to sever the wires. The buttonboard is connected to the motherboard by the wires.

Step 4




- Remove the windshield bracket mount.

Step 5 — Buttonboard




- Remove the four 4.8 mm Phillips #00 screws from the buttonboard.

Step 6



- Lift buttonboard to expose silver button plate.

Step 7 — Buttons



- Remove the silver button plate by gripping one of the corners and pulling up.

To reassemble your device, follow these instructions in reverse order.

This document was last generated on 2017-07-31 12:03:06 AM.